

EB25 Front trim unit

<i>Virutex</i>			
50 Hill Street, #509			
Southampton, NY 11968			
Phone: 1-800-868-9663			
Fax: 631-537-2396			
		<u>Model: EB25-Front Blade Assembly</u>	
			2008
<u>POS.</u>	<u>CODE</u>	<u>ITEM</u>	<u>List price</u>
PARTS LIST			
6346048-FRONT TRIM UNIT			
POS.	CODE	ITEM	
1	6307031	FRONT TRIM UNIT BASE	\$86.25
2	1610018	BUSHING KH1228A	\$30.00
3	1628072	SPRING CAP	\$2.81
4	1626045	SPRING	\$2.81
5	1688015	RETAINING RING D.12	\$0.94
6	1628089	GUIDE ROD	\$13.75
7	1675031	HEX. SOCKET SET SCREW M.6X10	\$1.00
8	1606056	MAGNET HOLDER	\$70.00
9	1626042	SPRING	\$3.75
10	3870033	PAN HD. TAPPING SCREW 4X5/8 PH.B.	\$1.00
11	4445030	MICROSWITCH	\$38.75
12	1628074	BOLT	\$16.13
13	1383003	WASHER AET D.6,4	\$1.00
14	1675035	HEX. SOCKET HD. CAP SCREW M. 6X10	\$2.81
15	1650049	MAGNET ASS'Y 220 V. 50 Hz.	\$179.00
16	3885004	SELF-LOCKING HEX. NUT M.8	\$1.88
17	6331016	MOVABLE BLADE	\$68.75
18	1628071	PIVOT SCREW	\$18.75
19	1673018	HEX. SOCKET FLAT HD. SCREW M. 6X20	\$1.00
20	1631005	FIXED BLADE .(R)	\$66.00
21	1322078	LOCK NUT	\$6.56
22	1650050	CORD ASS'Y FOR FRONT TRIMMING STATION	\$13.13
23	2385005	HEX. NUT M.4	\$1.00
24	9580005	WASHER	\$1.88
25	4473021	FLAT HD. SCREW M. 8X35	\$1.13
26	2023036	WASHER	\$1.88
27	4434029	MICROSWITCH HOLDER	\$3.75
28	1372016	PAN HD. SCREW M. 4X6 PH.	\$1.00
29	4428042	GUIDE ROD	\$13.75
30	1680026	WASHER	\$1.00
31	6371025	HEX HD. SCREW M.4X12	\$1.88
If the movable blade #6331016 does not come forward			

EB25 Front trim unit

	to cut the tape; it could be the microswitch #4445030 lever	
	is not letting the white piece come out fully to make a	
	clicking sound.	



